

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 39 N.R. 3W


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 20, 21, 28, and 29.

CORNER MONUMENT 1" pipe with 4" brass cap.

DATE MONUMENT PLACED AND WITNESSED April 24, 1961

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

<u>12" Spruce</u>	<u>-</u>	<u>N47E</u>	<u>-</u>	<u>62.2 ft.</u>
<u>8" Spruce</u>	<u>-</u>	<u>N15W</u>	<u>-</u>	<u>32.8 ft.</u>

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found by Forestry Division survey crew while making a survey in this area. Found 3/4" pipe at corner, apparently used in surveys in Sections 20 and 21. Cedar stumps in place for government BTs, but no marks. Found stake point about 2 ft. below surface when setting corner.

SURVEYOR'S SEAL

SIGNED *Kenneth Stelling* DATE May 23, 1961  
REGISTERED LAND SURVEYOR