

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 36-37 NR. 19 W. . .

Delta

_____ COUNTY

DESCRIPTION OF CORNER Section Corner common to Sec.'s 3-4-33-34 _____

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap _____

WITNESSES TO CORNER 9" Cedar N 25° W 76 links _____

15" Hard Maple N 70° E 44 links _____

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set corner by measuring recorded distance 7.50 chs. from original meander corner between Sec.'s 33/4.

Meander corner lies 7.50 chs. west of section corner.

Numerous cedar stumps in vicinity but could find no evidence of original B.T.s.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/26/57
REGISTERED LAND SURVEYOR