SURVEY & REMONUMENTATION

JAN 31 2001

SECTION

Approved By Deita County Land Survey Remonumentation
Peer Group Under Act 345 of

	1	001	GIU	up u	ILICIE	r Ac	13	10 CF	
P.,	A_	Of 1	990	On.	12	/z	2	2000	7

	•			
D 1 001100		1 19 /		
P.A. Of 199	KILIN.	/	フユ	20 <i>CO</i>
	V V/	, <u></u> ,		20 <u>-0</u>
/ . / 4	$a{n}l^{-1}$	0 / "	_	

L	AND	COR	NER R	RECO	RDA	ATIC	ON CE	RTIF	ICA	Ŧ
	Filing	a Real	uireme	ent of	Act	74.	Mich.	P.A.	197	0

But Miles & Miles

E Mullehmeling

For corners in	Filing Re	equirement of Act	74, Mich. P.A. 197	10 acting	Chairmen /	
DELTA	Located in:	Corner Code #				
(County)	Looding III.	/	· union company			
1. Public Land Survey	T 37 NR 19 k T 37 NR 19 k T R			RECORDED	January 200)1
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R 1-02 [W1/4 COR SEC	21 I-03 (NW COR	SEC 11]	DELTA COUNTY	PAGE_, 245	
4. Lot No, Reco						
5. Private Claims				A B C D E	E F G H I	J K L M
				2 6 5 3	3 -	2 — — 1 —
I, M.P. DAVIS requirements of P.A. 74, Michig conformance with regulations an United States Department of the that the corner points mentioned Board of Land Surveyors or be recovered, found as expressed by	pan P.A. of 1970, the corner point of rules therefore as required in the Interior, Bureau of Land Managed in lines 3, 4 and 5 above were by a Decree of a Court of Lav	nts mentioned in lines 1 he current manual of sun ement or by a decree of a In conformance with the	and 2 above were in rey instructions of the Court of Law and /or rules of the Michigan	4 - 7 - 8 - 5 - 6 - 18 - 17 - 7 - 8 - 19 - 20 - 1	9 10 10 11 11 11 11 11 11 11 11 11 11 11	111213141312324
NOTE: Not more than 2 cor	mers, all in the same town and	d range, may be record	ed	9		-
on this certificate.				10 30 29	28 27 2	26 25
				11 32 32	33 34 3	
	:			13		
A. Description of original marginal marginal in I-02 [W1/4 COR SEC 2] ALGERN				NATAWADACK 100 SA	.7° = 16 1 TNKS)	
M.S.McNABB-1920-ID BY	ORIGINALS-MADE + IN STONE	E LEDGE (SPRUCE 3" M	L NOU NOOF ON LINK	S)/RAISAM 100 S65	"W 10 LINKS)	
	idence found and/or method	d applied in restoring (or reestablishing corr	ner:	OF MIC	NICH.
B. Description of corner ev 1-02 [W1/4 COR SEC 2] FOUND				≥ 1	DAVIS	
STONE LEDGE AS IT APPE POSITION 6" NORTH OF A	EARS TO HAVE FRACTURED A SWOOD POST AS THIS POSITION TO HIS N1/16 COR & THE NW PERPETUATION OF THE POSIT	NUMBER OF TIMES OVER N CHECKS WELL WITH ' COR OF SEC 2. ACCES	THE RECORDS OF MCNAPTED THIS LOCATION	BB FOR	LAND SURVE	YOR S
I-03 [NW COR SEC 11] FOUND ID SAME AS THAT SET II ACCEPTED EXISTING MONI POSITION OF THE ORIGIN	N 1984 BY T.OBRIEN FROM UMENT AS BEING THE BEST A	HIS RECORDED BI'S WI	TILB AKE NUW DUIR D	SEOM DOMUS.	LAND LAND	SUL
C. Description of monumen						
I-02 SET IN A DRILL HOLE II CEDAR 11" WEST 18.21'	BALSAM 08" BA N20'E	18" REBAR W/A 3-1/ LSAM 07" WHI S75"E 29.56'	4' ALUM CAP STAMPE TE BIRCH 06" S15"W 27.96'	O TO ID THE CORNE	R POSITION.	
I-03 SET OVER EXISTING MON CEDAR 13" S85°W 11.04'	CEDAR 09" CEDAR 2 N41°E S85°E 23.04' 23.44'	\$12 W \$12'W 4.16'				
NOTE: BEARINGS TO REFEREN	CE OBJECTS ARE MAGNETIC-D	ISTANCES ARE TO A N	AIL W/A DELTA COUN	TY REFERECNE TAG,	UNLESS OTHERWIS	E NOTED.
	Davis	-	Date/ <i>C</i>	2/23/00		
Surveyor's Michigan License			_			
			· •			