STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	DeltaCOUNTY	ŕ
	T 37 N R 24 W	
DESCRIPTION OF CORNER	Section corner for sections 32/33	
CORNER MONUMENT	1" iron pipe with 4" aluminum cap	
DATE MONUMENT PLACED AND V	NITNESSED 6/24/69, F. J. Bray	
WITNESSES TO CORNER	8" Cedar (S 33) (NBT) S 80° E, 26½ links	· · · -
N	9" Cedar (S 32) (NBT) S 49° W, 49½ links	
	AND	
CIRCLE CORNER REGISTERE	D.	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was reestablished by double proportioned measurement between section corners one mile to north and west and 1/4 corners 1/2 mile to east and south. Chopped out stump faces corner as set. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNE

REGISTERED LAND SURVEYOR

DATE 6/27/69

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing