STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	<u></u> I	DeltaCOUNTY
	Τ.	<u>37 N</u> R <u>24 W</u>
DESCRIPTION OF CORNER	$1/4$ corner for sections $\frac{21}{28}$	
	1" iron pipe with 4" aluminum cap	ρ
DATE MONUMENT PLACED AND WITNESSED 6/18/69, F. J. Bray		
WITNESSES TO CORNER 7" Cedar (1/4 S) (NBT) N 57° W, 23½ links		
2 8	12" Cedar (1/4 S) (NBT) N 30° E, 2	26 links
	AND	
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section:corners to east and to west. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

IGNED Trans L. Sour

DATE 6/26/69

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing