## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

			elta	COUNTY
		Т3	37 N	R _ 24 W
DESCRIPTION OF CORNER	Section corner for sections	20/21 29/28		
CORNER MONUMENT	1" iron pipe with 4" aluminu	им сар		
DATE MONUMENT PLACED AND WITNESSED 6/18/69, F. J. Bray				
WITNESSES TO CORNER	6" cedar (S 21) (NBT) N 72°	E, 05 1	inks	
2 8	7" cedar (S 20) (NBT) N 84 <sup>0</sup>	W, 11 1	inks	
	AND			
CIRCLE CORNER REGISTERED				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was reestablished by double proportioned measurement between section corners one mile to east and to west and 1/4 corners 1/2 mile north and 1/2 miles to south. Squared cedar tree near. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED REGISTERED LAND SURVEYOR

DATE \_\_\_\_

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing