

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 37 N R 24 W

DESCRIPTION OF CORNER E 1/16 corner for sections $\frac{6}{7}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6/19/69, F. J. Bray

WITNESSES TO CORNER..... 4" B. Spruce (E 1/16) (BT) S 83° E, 24 links



3" B. Spruce (E 1/16) (BT) S 21° W, 47½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed on line and midway between section corner to east and 1/4 corner to west. Corner lies on east side of old winter logging road.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE 6/26/69

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68