STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

T <u>37 N</u> R <u>24 W</u>	'
	_
DESCRIPTION OF CORNER 1/4 corner for sections 21	
CORNER MONUMENTl" iron pipe with 4" aluminum cap	
DATE MONUMENT PLACED AND WITNESSED 6/27/69, F. J. Bray	
WITNESSES TO CORNER 12" W. Pine (1/4 S) (NBT) N 38° E, 42 links	
5" Hemlock (1/4 S) (NBT) S 55° W, 34 links	
AND CIRCLE CORNER REGISTERED	<u> </u>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners to east and to west. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

GNED REGISTERED LAND SURVEYOR

DATE <u>6/30/69</u>

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing