

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Delta COUNTY  
T 37 N R 24 W

DESCRIPTION OF CORNER Section corner for sections <sup>16/15</sup> 21/22

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6/25/69, F. J. Bray

WITNESSES TO CORNER..... 12" Cedar (S 22) (NBT) S 81° E, 07 links



10" Cedar (S 21) (NBT) S 77° W, 15½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed on line between section corners to east and west and the proportioned distances as per original survey. Corner as set checks well with corners in area and blazes on trees face corner as set. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray DATE 6/30/69  
REGISTERED LAND SURVEYOR  
Frank J. Bray

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68