STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	<u>Delta</u>	COUNTY
	T37 N	R 24 W
<u>15</u>		
DESCRIPTION OF CORNER $\frac{1/4 \text{ corner for sections}}{22}$		
CORNER MONUMENT 1" iron pipe with 4" aluminu	m cap	
DATE MONUMENT PLACED AND WITNESSED 6/25/69, F. J. Bray		
WITNESSES TO CORNER 6" Cedar (1/4 S) (NBT) N 45°	E, 143 links	
8" Cedar (1/4 S) (NBT) S 60°	E, 16 links	
AND		
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners to east and to west. Blazed trees in vicinity. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED REGISTERED LAND SURVEYOR

DATE 6/30/69

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing