## STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

## LAND CORNER RECORD

	_ Delta	COUNTY
	T 37 N	R24 W
DESCRIPTION OF CORNER	1/4 corner for sections 9/10	
CORNER MONUMENT	1" iron pipe with 4" aluminum cap	
DATE MONUMENT PLACED AND WITNESSED _ 7/1/69, F. J. Bray		
WITNESSES TO CORNER	8" Cedar (1/4S) (NBT) N 06° W, 45½ links	
) o r	12" W. Pine (1/4S) (NBT) S 51° E, 51 links	<b>5</b>
	AND	
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners to north and to south. Wood post and blazed trees invicinity. No original evidence found.

SURVEYOR'S SEAL

**DISTRIBUTION:** 

REGISTERED LAND SURVEYOR Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing