

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Delta COUNTY
38
T 37 N R 24 W

DESCRIPTION OF CORNER Section corner for sections $\frac{33}{34}$ T38N R24W
 $\frac{4}{3}$ T37N R24W

CORNER MONUMENT 1½" I.D. x 30" iron pipe buried in gravel road.

DATE MONUMENT PLACED AND WITNESSED 7/2/69, F. J. Bray

WITNESSES TO CORNER..... (Center of top of corner fence post) South, 29 links



Guard rail post. S 71° E, 44 links

Guard rail post. N 70° E, 46 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed in line with fence corners to north and to south and in $\frac{1}{2}$ of E-W gravel road; adjacent owner claims this to be location of corner. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR

DATE

7/16/69

Frank J. Bray

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68