## STATE OF MICHIGAN **DEPARTMENT** 0F NATURAL RESOURCES

## LAND CORNER RECORD

	COUNTY
	T 37 N R 24 W
DESCRIPTION OF CORNER _	1/4 corner for sections 21/22
CORNER MONUMENT	1" iron pipe with 4" aluminum cap
DATE MONUMENT PLACED AND WITNESSED 7/9/69, F. J. Bray	
WITNESSES TO CORNER	8" Cedar (1/4 S) (NBT) N 51° W, 07 links
2 2	9" Cedar (1/4 S) (NBT) S 70° E, 18 links
	AND
CIRCLE CORNER REGISTERED	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners to north and to south. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing