

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Delta COUNTY


T 37 N R 24 W

DESCRIPTION OF CORNER Section corner for sections $\frac{21}{22}$
 $\frac{28}{27}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6/10/69, F. J. Bray

WITNESSES TO CORNER..... 7" Cedar (S 22) (NBT) N 40° E, 33 links



9" Cedar (S 27) (NBT) S 19° E, 38 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from rotted wood post. Found points of two wood post which check with rotted cedar stumps the proper distance and bearings. Blazed and notched trees in vicinity.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR

DATE 6/25/69

Frank J. Bray

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68