

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Delta COUNTY  
38  
T 37 N R 24 W

DESCRIPTION OF CORNER 1/4 corner for sections <sup>34</sup> 3 T38N R24W T37N R24W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7/8/69, F. J. Bray

WITNESSES TO CORNER..... 9" Cedar (1/4 S) (NBT) N 33° E, 44½ links



7" Cedar (1/4 S) (NBT) S 02° E, 47 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed along fence post. Otto Lindquist, land owner, claims Marcus McNabb, R.L.S., placed a wood post at this point which had rotted. Corner lies in N-S fence line. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

*Frank J. Bray*  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

7/16/69

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68