MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 38-39 N.R. 18 W

| | | Delta | | COURTY |
|------------------------|--------------------------------------|------------|----------|--------------|
| DESCRIPTION OF CORNER | 1/4 corner between Sections 31 and 6 | | | |
| CORNER MONUMENT | 1" Pipe with 4 | Brass Cap | | |
| DATE MONUMENT PLACED A | ND WITHESSED | 9/9/60 | | |
| WITNESSES TO CORNER | 8" Cedar | (1/4s NBT) | N 84° E | 07 1/2 Links |
| N | 7" Cedar | (1/4s NBT) | N_11° W_ | 12 1/2 Links |
| T39N R18W | | | | |
| CIRCLE CORNER REGISTER | AND | | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between Section Corners. No evidence of original corner.

SURVEYOR'S SEAL