Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 19W __

			Delta	COUNTY
DESCRIPTION OF CORNER	South 1/8 corner for sections 4-5			
CORNER MONUMENT	3/8" X 24" iron bar			
DATE MONUMENT PLACED AND	WITHESSED			
WITHESSES TO CORNER	9# Cedar (BT)	s68°w	4.11	
N	10" Cedar "	n62°w	5.31	
1	ll" Cedar "	568°E	3.51	
CIRCLE CORNER REGISTERED	AND			

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed at proportionate distance and on line between 1/4 corner to north and meander corner to south.

SURVEYOR'S SEAL

SIGNED Silly D. Buckler

Signed March 14, 1962

REGISTERED LAND SURVEYOR

Billy D. Buckler