

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 38-39 N.R. 19W


Delta COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner for sections 4-33

CORNER MONUMENT 1" Pipe with 4" brass cap.

DATE MONUMENT PLACED AND WITNESSED 9-15-61 with D. St. Ours

WITNESSES TO CORNER..... 10" Cedar ($\frac{1}{4}$ S NBT) S75°E 23.6'



7" Hard Maple ($\frac{1}{4}$ S NBT) S35°W 27.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at old iron pin with pile of stones set by unknown surveyor.
Position checks well with other corners in area.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 14, 1962
REGISTERED LAND SURVEYOR
Billy D. Buckler