STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

| | DeltaCOUNTY |
|-----------------------|--|
| | 39 T <u>38 N</u> R <u>19 W</u> |
| DESCRIPTION OF CORNER | 34 T39N, R19W W 1/16 corner for sections 3 T38N, R19W |
| CORNER MONUMENT | 1" iron pipe with h" aluminum cap |
| DATE MONUMENT PLACED | WND WITNESSED 12/14/70 F. J. Bray |
| WITNESSES TO CORNER | 6" Gedar (BT) S կկ ^O W, 5.81 |
| N 3 | 14" (Twin) Cedar (BT) N 39° W, 14.9' |
| T38N R19W | AND |
| CIDCLE CODNED RECIS | rrpri |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to west and 1/4 corner to east.

SURVEYOR'S SEAL

SIGN

SIGNED Frank

DATE ____1/11/71

DISTRIBUTION:

REGISTERED LAND SURVEYOR

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68