

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Delta  
(County)

Located In:

Corner Code ##

- |                                       |                           |             |
|---------------------------------------|---------------------------|-------------|
| 1. Public Land Survey                 | T <u>38N</u> R <u>19W</u> | <u>G-2,</u> |
|                                       | T _____ R _____           | _____       |
|                                       | T _____ R _____           | _____       |
|                                       | T _____ R _____           | _____       |
| 2. Property Controlling in Section    | S _____ T _____ R _____   | _____       |
|                                       | S _____ T _____ R _____   | _____       |
| 3. Miscellaneous Property in Sec.     | S _____ T _____ R _____   | _____       |
|                                       | S _____ T _____ R _____   | _____       |
| 4. Lot No. _____, Recorded Plat _____ |                           |             |
| 5. Private Claims _____               |                           |             |

**Register of Deeds Stamp & File Number**

I, David B. Babbitt, in a field survey on 4/28, 19 86, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

- G-2. East 1/4 corner of Section 4.  
 Wood post.  
 Beech 12, N60E, 18 Lks.  
 Cedar 8, S50W, 10 Lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- G-2. Set by single proportion to the G.L.O. record as indicated on a drawing of survey by Billy D. Buckler, RLS, #8887, for Fayette State Park, dated 11/12/61.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G-2. DNR Monument.  
 4" cedar S49E, 16.25'  
 6" cedar N55E, 14.7'  
 4" cedar N5W, 30.9'  
 Corner fence post S65W, 46.8'

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by

*David B. Babbitt*

Date

7-8-86

Surveyor's Michigan License No.

RLS 21558