FEB 2 2 1996

COMMISSION

		Approved By Delta County Land Survey Remonumentation Peer Group Under Act 345 Of P.A. Of 1990 On Affective 3 o 199 3
LAND CORN	ER RECORDATION CEF	STIFICATE Metheling
Filing Requir	rement of Act 74, Mich.	P.A. 1970
ed in;	Corner Code ##	DELTA COUNTY
N R 23 W	A-7 & K-13	LIBER 1 PAGE 332
N R 23W	(R-1)	93 DEC - 2 MM 9: 00
R R		Water a Elona REGISTER OF DEEDS
R R		Register of Deeds Stamp & File Number
States Departm that the corner penigan Board of Lumented, re-modern and essories and/o - 1845 - (BEEC ACE, RESET 5' 1')	1970, the corner points mentice rules therefore as required in the interior, Bureau of the interior, Bureau of the interior, Bureau of the interior, Bureau of the interior of the interior, Bureau, 4 a.and Surveyors or by a Decree numented, recovered, found range, may be recorded as subsequent restoration:	ned on the .and .and .and .and .and .and .and .and
DEDOM COUNTY	ed in restoring or reestabl ROAD SURFACE, AS INDICATE	D BY ROAD IMPROVEMENTS & OCCUPATION NO EVIDENCE OF
		ITION OF THE ORIGINAL CORNER
>/÷" BRASS PIN IL & FAITHFUL R	CENTER BY RETRACEMENT OF T BESTABLISHMENT OF THE POSI	THE S. LINE OF SEC 36 AS PER CITY ENGINEERS RECORDS

Filing Requirement of Act 74 For corners in DELTA Located In: Corner Code 1. Public Land Survey T 39 N R 23 W 2. Property Controlling in Section S T Miscellaneous S .. T B Property in Sec. S Т 4. Lot No. ., Recorded Plat Private Claims - A-7 [NW COR SEC 19] K-13 [SW COR SEC 36] -Same as K-1 T38N R23K M.P. DAVIS in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner poi in lines 1 and 2 above were in conformance with regulations and rules therefore as ru current manual of survey instructions of the United States Department of the Interior, B Management or by a decree of a Court of Law and/or that the corner points mentioned in li above were in conformance with the rules of the Michigan Board of Land Surveyors or by Court of Law; established, re-established, monumented, re-monumented, recover NOTE: Not more than 4 corners, all in the same town and range, may be reon this certificate. Description of original monument and accessories and/or subsequent rest A-7 [NW COR SEC 19] WOOD POST - JOHN BURT - 1845 - (BEECH 8"-S15°W-51 LIN M.S. McNABB-1914-FOUND WOOD POST IN PLACE, RESET 5' IRON PIPE (HEMLOCK K-13 [SW COR SEC 36] WOOD POST-WM. BURT-1844 [CEDAR 10"-N38"E-6 LINKS) (CE M.S. McNABB-1936-FOUND CONC. MON IN PLACE, ID FROM ESCANABA CITY ENGI Description of corner evidence found and/or method applied in restoring or A-7 [NW COR SEC 19] FOUND I.P. IN PLACE, 22" BELOW COUNTY ROAD SURFACE, AS MCNABB'S HEMLOCK BT'S FOUND ACCEPTED EXISTING NON AS BEING A CAREFUL & FAITHFUL REESTABLISHMENT OF K-13 [SW COR SEC 36] FOUND 8" CONC MON W/A 3/4" BRASS PIN CENTER BY RETRACES ACCEPTED EXISTING MON AS BEING A CAREFUL & FAITHFUL REESTABLISHMENT OF MIC M. P. DAVIS LAND SURVEYOR C. Description of monument for corner and accessories established to perpetuate locating the position of the NO. A-7 RAISED TO ROAD SURFACE W/A MONUMENT BOX AND A 5/8" X 18" REBAR W/A ALUMN CAP STAMPED TO ID THE CORNER POSET OF LAND SURVEY MONUNENT SIGN POST N52°W S61°W EAST 32/201 132.75 33.0' (TO FACE) K-13 DID NOT DISTURB EXISTING MONUMENT W. BIRCH 7* COR FENCE POST SURVEY HONUMENT SIGN POST N7°W \$39°E

N45°E

1.60' (TO FACE)

NOTE: BEARINGS TO REFERENÇE OBJECTS ARE MAGNETIC & DISTANCE ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS NOTED OTHERWISE

25.77

Surveyor's Michigan License No.

13.88' (TO FACE)