SURVEY & REMONUMENTATION

SEP 1 3 1994

COMMISSION

Approved By Delta County Land Survey Remonumentation

Peer Group Under Act 345 Of Of 1990 On July 3, 1994 The Releaseling

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich PA 1970

| | | i ming riequi | rement of Act 14, mich. | 1.74 1070 | | | | | |
|---------------------------|--|--|--|--|-----------------------|----------------------------|----------|-------------|-----------------|
| ror | corners in DELTA | Located In: | Corner Code ≠≠ | | | | | | |
| | (County) | | | | | | | | |
| 1. | Public Land Survey | T <u>38 N</u> R <u>24 N</u> T R T R T R | B-5 (B-7) | Wester. | clock AM | in Liber <u>8</u> | Page | 35 | |
| 2. | Property Controlling | S T R | | Daita Cour | nty, Michiga | an. | | | |
| | in Section | S T R | | | | | | | |
| 3. | Miscellaneous | S T R | | Regis | ter of Dec | eds Stam | o & File | Numb | er |
| | Property in Sec. | S T R | | | | | | | |
| | Lot No, Privatę Claims | B-5 [N1/4 COR S.18] B-7 [N1/ | | | A B C | 0 E F | G H | J J - 2 - | K L N |
| 1 | M.P. DAVIS | _ , in a field survey on | JULY 19 9 | 14 | 5 1 | - 8- 9 | 10- | <u> </u> | 12- |
| in I cur Mai abo | hereby certify that under r ines 1 and 2 above were rent manual of survey ins nagement or by a decree ove were in conformance | equirements of P.A. 74, Michigan P.A. in conformance with regulations a tructions of the United States Depart a Court of Law and/or that the corrwith the rules of the Michigan Board re-established, monumented, re | A. of 1970, the corner points men and rules therefore as required artment of the Interior, Bureau her points mentioned in lines 3, of Land Surveyors or by a Dec | ntioned d in the of Land 4 and 5 tree of a und as | 6 18 7 8 19 9 0 30 30 | -17 16 -20 21 -29 28 | 22-27- | 23-26- | 24-25- |
| NO | | corners, all in the same town a | and range, may be recorde | ·u | 1 | + | ++- | +-+- | + |
| | on this certificat | e. | | 1 | 2 | _3'2 | | | 36_ |

- Description of original monument and accessories and/or subsequent restoration:
 - B-5 [N1/4 COR S.18] WOOD POST GEORGE ADAIR, D.S. 1852 (TAMARACK 5"-N71'E-16 LINKS) (TAMARACK 8"-S30'W-19 LINKS) M.S.McNaBB-1946-SET WOOD POST-ESTABLISHED PROPORTIONATE DISTANCE BETWEEN CORNERS (CEDAR 7"-EAST 9.5') (CEDAR 5"-N12"W-26')
 - B-7 [N1/4 COR S.19] WOOD POST GEAORGE ADAIR, D.S. 1852 (BEECH 6"-N26"W-23 LINKS) (BEECH 7"-S46"E-18 LINKS) NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY OR MONUMENTATION
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - B-5 JN1/4 COR S.18] CHAINED EAST FROM NW COR SEC 18 @ 1265' M/L FOUND McNABB'S 1946 W1/16 COR (CEDAR POST SCRIBED 1/8) AND A 2585' M/L FOUND REMAINS OF MCNABB'S WOOD POST & HIS CEDAR BT (EAST 9.5') WHICH IS STILL GREEN. ACCEPTED EXISTING MONUMENT AS BEING A CAREFULL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.
 - B-7 [N1/4 COR S.19] FOUND IN PLACE, AS INDICATED BY E-W COUNTY ROAD IMPROVEMENTS & N-S OCCUPATION AN IRON BOLT, ORIGIN UNKNOWN. CORNER POSITION CHECKS WELL TO OCCUPATION TO THE EAST & WITH GLO DISTANCES TO ADJOINING CORNERS E & W. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - B-5 REPLACE WOOD POST W/A BERNTSEN AINB30 ALUMN MONUMENT WITH THE CAP STAMPED TO ID THE CORNER POSITION.

| _ | | | | | |
|---|-------------|-----------|--------------|-------------|---------------------------|
| | TAMARACK 6" | CEDAR 10" | .TAMARACK 9' | TAMARACK 9" | SURVEY MONUMENT SIGN POST |
| | N3°W | EAST | S9°W | N82°W | NORTH |
| | 36.42' | 9.50' | 24.981 | 20.59' | 1.93' (TO FACE) |

B-7 SET, OVER EXISTING MON, A 5/8" X18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE COR POSITION & RAISED TO RD SURFACE W/A MON BOX

MAPLE 20% SURVEY MONUMENT SIGN POST POWER POLE N6°E S37°E SOUTH

36.64' (TO FACE) 22.45' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC - DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS NOTED OTHERWISE

Date 7/11/94 Surveyor's Michigan License No. 16926