

FEB 2 2 1996

NORTH

27.84

Signed by *A.P. Laui 1/9/96* 

Surveyor's Michigan License No. 16926

## Approved by Delta County Land Survey Remonumentation Peer Group Under Act 345 Of A.O. 1990 On 177 , 1996 Market Schmaling Acting American LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 For corners in DELTA Located In: Corner Code ## T 38 N R 24 W & B-11 1. Public Land Survey 9:0° o'clock AM in Liber 8 Page 119 \_\_ R R ita County, Michigen R 2. Property Controlling S. R in Section R Miscellaneous s Register of Deeds Stamp & File Number s Property in Sec. 4. Lot No. \_\_ , Recorded Plat 5. Private Claims H-7 [N1/4 COR S.22] H-11 [N1/4 COR S.34] I, M.P. DAVIS , in a field survey on 12/95 7/94 , 19 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: H-7 [R1/4 COR S.22] GEORGE ADAIR, D.S. - 1852 - WOOD POST - (TAMARACK 04\*-N75\*W-18 LINKS) (SPRUCE 03\*-S451/2\*E-45 LINKS) NO RECORD EVIDENCE OF SUSEQUENT CORNER RECOVERY OR HONUMNETATION H-11 [N1/4 COR S.34] GEORGE ADAIR, D.S. - 1852- WOOD POST - (CEDAR 10"-N81"B-09 LINKS) (MEMLOCK 10"-S81"W-09 LINKS) NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY OR MONUMENTATION Description of corner evidence found and/or method applied in restoring or reestablishing corner: H-7 [N1/4 COR S.22] NO CORNER EVIDENCE FOUND. SET CORNER AT HIDPOINT BETWEEN SECTION CORNERS OF MIC 1/2 HILE BAST AND WEST. CORNER IS LOCATED IN A DENSE SPRUCE/TAMARACK SWAMP, 12' M/L NORTH OF A E-W WOODS ROAD. DAVIS LAND SURVEYOR H-11 [N1/4 COR S.34] NO CORNER EVIDENCE FOUND. REBSTABLISHED CORNER POSITION FROM ANCIENT LINES OF NO. OCCUPATION. EXTENDED LINE EAST FROM NW COR OF S.34 THRU CORNER FENCE POST FOUND AT THE W1/16 16926 (FENCE LINE E-W & S) AND SET THE 1/4 CORNER ON THIS LINE AT A DISTANCE EAST OF THE W1/16 THAT IS EQUAL TO THE DISTANCE THAT THE W1/16 IS EAST OF THE NW CORNER OF S.34. ACCEPTED THIS POSITION AS ED LAND THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-7 SET BERNTSEN AINB30 ALUHN. MONEMENT W/A 3'/4" CAP STAMPED TO ID THE CORNER POSITION. SPRUCE 3" SPRUCE 4" SPRUCE 3" SPRUCE 4" SURVEY MONUMENTS. SPRUCE 4\* SURVEY MONUMENT SIGN POST N38.A \$54'E N63°E S63#° 10.25' 17.62 10.76 12.60' H-11 SET BERNISEN AINB30 ALUMN MONUMENT W/A 31/4- CAP STAMPED TO 1D THE CORNER POSITION. SPRUCE 6° W.BIRCH 8° SURVEY MONUMENT SIGN POST 510°W. S64°W \$73°E. MAPLE 11°

Approved By Delta County

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC - DISTANCES ARE TO A MAIL IN THE CENTER OF THE OBJECT UNLESS NOTED OTHERWISE

2.24' (TO FACE)

Date \_ AN S, 1996

20.43'

LIBER

19.63'