

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 38. NR. 23. - 24 W

. D. e. l. t. a COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 25, 36, 30, and 31

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap.

WITNESSES TO CORNER 8" Cedar . . (S 30 NBT) . . N 48° E . . 33 Links

6" Cedar . . (S 25 NBT) . . N 43° W . . 19 Links

7" Cedar . . (S 31 NBT) . . S 74° E . . 28 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced from two Cedar stumps and one spruce stump
in proper position. Found old stake bottom in muck. Found by E. Dahlvik,
Sawyer, Stoll Timber Company.

Corner lies in swamp.

Corner was placed and witnessed February 3, 1960 with Dahlvik and J. Bastian.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 2/23/60 .
REGISTERED LAND SURVEYOR
Billy D. Buckler