MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_38_ NR_24_ W

	COUNT
DESCRIPTION OF C	ORNER 1/4 corner between Sections 25 and 26
DESCRIPTION OF CO	ORNER MONUMENT_1" Pipe with 4" Brass Cap
WITNESSES TO COR	RNER 8" Cedar _ (1/4s_NBT) _ N 76° E _ 24 Links
	6" Cedar _ (1/4s_NBT) _ S 37° W _ 10 1/2 Links_

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from two Cedar B. T. s bearing S 10° W 19 Links and N 50° E 17 Links. Both are stumps in fair condition.

Corner found by E. Dahlwik, Sawyer, Stoll Timber Company.

Corner was placed and witnessed February 3, 1960 with E. Dahluik, Escanaba and J. Bastian, Assistant District Forester.

SURVEYORS SEAL