

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 38N M.R. 24W


Delta COUNTY

DESCRIPTION OF CORNER 1/4 cor. for secs. 13 and 14

CORNER MONUMENT 1" iron pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 9/1/66 Everette Dahlvik

WITNESSES TO CORNER..... 7" Cedar (1/2S)(NBT) N50°W, 10 lks.



10" Cedar (1/2S)(NBT) S11°E, 37 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from original bearing tree, (cedar 9" N59°E, 12 lks.). Rotted and down but iron marks in lower face visible. This corner shown to me by Everette Dahlvik.

SURVEYOR'S SEAL

SIGNED F. J. Bray DATE 2/6/67  
REGISTERED LAND SURVEYOR