

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Delta COUNTY
T 38 N R 24 W

DESCRIPTION OF CORNER 1/4 corner for sections 27/26

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6/4/69, F. J. Bray

WITNESSES TO CORNER..... 8" Cedar (1/4 S) (NBT) S 66° E, 41 links



8" Cedar (1/4 S) (NBT) S 40° W, 34½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from cedar B.T. portion of scribe marks on upper face, lower face rotted. Tam BT is now rotted stump. Three wood post near. Blazed trees and squared cedar stub. Shown to me by Foresters Zuidema and Conley.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

6/25/69

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68