STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

			Delta		_COUNTY
		T .	38 N	R.	24 W
DESCRIPTION OF CORNER	26 1/4 corner for sections 35				
CORNER MONUMENT 1" iron pipe with 4" aluminum cap					
DATE MONUMENT PLACED AND WITNESSED 6/10/69, F. J. Bray					
WITNESSES TO CORNER 14" W. Pine (1/4 S) (NBT) N 69° W, 42 links					
N 3'5	8" Cedar (1/4 S) (NBT) N 78°	•		···-	
	McNabb's - 8" Cedar (BT) S 30	0 <u>0 M</u>	, 23 links		
CIRCLE CORNER REGISTERE	D				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from wood post and old rotted scribed post. Possibly set by M. McNabb in 1924. He mentioned original maple B.T. in 1924. No evidence of tree at the present time. Rotted pine stump checks for other B.T. Blazed trees near.

SURVEYOR'S SEAL

SIGN

IGNED REGISTERED LAND SURVEYO

DATE __6/25/69

DISTRIBUTION: REGISTERED L. Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing