LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	İ	ORNER CODE NUMBER	
1. PUBLIC LAND SURVEY =	T. 38 X, R.	24 🐺 K-	2	
2. PROPERTY CONTROLL- ING IN SECTION—2	,T 38 % . R	24 W3	,10	
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. S., R.	E.		
4. LOT NO , RECO	RDED PLAT			
5. PRIVATE CLAIMS				REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in field survey on June 1 restored as expressed below at of survey instructions of the U court of law. Furthermore,	lines 1 and 2 ab 19	ove (identified stablished, re- with regulation of the I points mention estored, establioard of Regist	d with circles on index established, monument ins and rules therefore a nterior, Bureau of Landined in lines 3,4 and 5 lished or re-established tration for Land Surveyor	P.A.74, Michigan P.A. of 1970, code diagram – over) were, in a ed, re-monumented, recovered or is required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in contrast or, by a Decree of a Court of
A. Description of original mon	ument and access	ories and/or s	ubsequent restoration:	
K-2 Woodpost:) (0:4			
Cedar 12 Cedar 8		22 link 45 link		
witnesses · McN	s set from 3 ab witnesses,	old post po Tam. 6 NNI by proporti	oints and remains 13', Tam. 7 SW b	at Marcus McNab
10 This corner was	s set by mid- rner north.	point and o	on a line between	section corners
C. Description of monument f	or corner and acc	essories estat	olished to perpetuate loc k 10 1½" pipe All	cating the position of the corner: bearings-magnetic
K-2 4 Cedar (38) (NBT)	876 ⁰ E N20 ⁰ E	10.8'	
3 4" Cedar (N 4" Cedar (N	1/16) (BT) S 1/16) (BT) N	69°E	8.1 ¹ 19.0 ¹	
10 4" Cedar (8 4" Cedar (8	1/16) (BT) N 1/16) (BT) S	39°E 16°E	7.3' 0.5'	
SIGNED BY	<u></u>		DATE	
SUDUEVOD'S MICHIGAN RE	GISTRATION NO.			(SEAL)
FOR STATE AND UNITED ST				<u> </u>
SIGNED BY	CHIEF OF SURVEY	PARTX	DATE	
APPROVED AND SIGNED BY		6 X Zon	DATE	6/13/23