LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	CORNERS OF -: LOCATED IN -:			CORNER COD	E NUMBER	
1. PUBLIC LAND SURVEY	T 38	N. R. 24	_ W.	K-7, K-8,	<u>L-7</u>	
2. PROPERTY CONTROLL ING IN SECTION	,T.	N. S., R	_ E. _ W.			
3. MISCELLANEOUS PROPERTY IN SECTION	T	N. S., R	_ E.			
4. LOT NO	, RECORDED PLA	T'			·	
5. PRIVATE CLAIMS						REGISTER OF DEEDS STAMP AND
do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:						
A. Description of origina	al monument and	accessories	s and∎√	or subsequent	restoration:	
K-7 Woodpost:	Hemlock Hemlock	11 N	31 ⁷ 0	W 36	links links	
•	Hemlock Hemlock		1 47 S	_	links links	
	Cedar Tamarack		66		links links	
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: K-7 This corner was set by double proportionate measurement from corners & mile north, 1 mile south, & mile east and 1 mile west. Corner lies 29.0' at center line of winter rd.						
K-8 This corner was set mid-point and on a line between section corners north and south. No evidence of original corner.						
L-7 This corner was set from two original bearing tree stumps. Both in poor condition, scribe marks and axe marks visible.						
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: All bearings are magnetic All 1 iron pipe with 4 aluminum cap						
K-7 5" Cedar 6' Cedar	(824) (NBT) (823) (NBT)	833°E 557°W		11.1' 12.1'		
4" Hemlo	ine (1/28) (NB) ck (1/28) (NB)	r) s 7°w		23.2' 9.5'	o	
L-7 4" Cedar	ck (Squared (1/28) (NBT) (1/28) (NBT)) N60°W	10	•5†	E 2.1.	
					DATE	<u>-</u>
SURVEYOR'S MICHIGAN REGISTRATION NO (SEAL)						
FOR STATE AND UNITED STATES AGENCIES:						
SIGNED BY	CHIEF OF	SURVEY PARTY			DATE	
APPROVED AND SIGNI	ED BY	ICHIGAN REGIST	EASO LA Bray	AND SURVEYOR	DATE <u>4</u>	(SEAL)