SECTION

32.51

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

والمعاده والمعارض الواء

Approved By Delta County	
Lang Survey Remonumentation	-
י סטו שוחות ותתפי מהו מגב הני	
PA-91 1990 On 3-3 199	Ŧ
+ 1 1 1 1 1 1 1 1 1 1	<u>, </u>
and B. Bather	`

Fo	or corners in				Chairman	_
	DELTA	Located In:	Corner Code ##			
	(County)		000. 0000	Residen Mai	L 1949	
1.	Public Land Survey	T 39 N R 18 W	_F-5_/	1 9:00 m	AM.	
		T 39 N R 18 N	F-7V	9	(Fig. 150	
		T R		1 9 P	W	
2.	Property Controlling	TR STR		Let Custome 32 Cold	CANE	
	in Section	S T R		. , ,		
3.	Miscellaneous	STR		Register of Deads 1	Stamp & File Number	
	Property in Sec.	S T R		- Trogister of Deeds t		
4.	Lot No.	, Recorded Plat			_	
				A B C D	E F G H I J K L	-
		T 5 (NI /A 200 ANA NC) - N 7 two	14 00D 000 011	2 6 5	+ 4 - + 3 - + 2 - + 1 -	
		F-5 [N1/4 COR SEC 16] F-7 [N1	/4 COR SEC 21)	1-1-1-	 	-
1	M.P. DAVIS	, in a field survey onFEBR	UARY19 99	4	9 10 11 12	
do	hereby certify that under	requirements of P.A. 74, Michigan P./	 of 1970, the corner points mentior 	ned e		_
		e in conformance with regulations a structions of the United States Depa		10-13-14-13-13-13-13-13-13-13-13-13-13-13-13-13-		
Ma	inagement or by a decree	of a Court of Law and/or that the corr	ner points mentioned in lines 3, 4 an	d5 8 10 00		_
		with the rules of the Michigan Board			21 22 23 - 24	_
	ourt of Law; established pressed below:	d, re-established, monumented, re	-monumented, recovered, found	as 10 30 39		
		4 corners, all in the same town a	and comes were the comes of	11 - 1	25-25-1-25-1-25-1	_
140	on this certifica		and range, may be recorded	12 31 32		
				13 1 1	33 34 35 36	_
Α.	Description of origin	al monument and accessories ar	nd/or subsequent restoration:	10 L		
	F-5 [N1/4 COR SEC. 16]] A.MERRYWEATHER, DS-1848-SET WOOD	D POST (IRONWOOD D6" N53°W 22 L	INKS)(BEECH 10" S20"E 2	5 LINKS)	
	T.0'BRIEN-1980-SET	F RR SPIKE IN C/L OF E-W COUNTY F	ROAD & IN LINE WITH FENCES N-S	(PP \$73°W 96.2')(ANCHOR	BOLT IN FENCE COR N4°E	

- F-7 [N1/4 COR SEC 21] A.MERRYWEATHER, DS-1848-SET WOOD POST-(CEDAR 16" S64"W 17 LINKS) (CEDAR 12' N75"E 25 LINKS)
 T.O'BRIEN, RLS-1980-L.2 PG. 406 LCR'S-FD IRON SPIKE (FENCE N & S) PP S11"W 41.1' FENCE POST N6"W 32.1'
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- F-5 [N1/4 COR SEC. 16] FOUND IN PLACE, IN APPROX C/L OF E-W COUNTY ROAD AND IN LINE WITH FARM FENCES N-S A RR SPIKE. ID CORNER MONUMENT FROM BT'S REC'D AT L.2 OF LCR'S PG 406. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.
- F-7 [N1/4 COR SEC 21] FOUND IN PLACE A 8" IRON SPIKE. ID CORNER MONUMENT FROM BT'S RECORDED IN L.2 OF LCR'S PG.406. CORNER MONUMENT FALLS ON APPROX C/L OF E-W COUNTY ROAD AND IN LINES WITH ANCIENT OCCUPATION LINES N

 ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner
 - F-5 REPLACED EXISTING MON W/A 5/8" X 18" REBAR W/A 31/4" ALUM CAP STAMPED TO ID THE COR POSITION & RAISED TO GRADE W/A MON BOX.

5/8" X 18" REBAR W/A 2" ALUM WIT CAP CEDAR 05" ASH 05" SURVEY MONUMENT SIGN POST N45"E S45"E S63"W N57'W SOUTH 25.00' 26.54' 69.79' 59.81' 30.80' (TO FACE)

F-7 REPLACED EXISTING MONUMENT W/A 5/8" X 18" REBAR W/A 31/4" ALUM CAP STAMFED TO ID THE CORNER POSITION.

ASH 06" ASH 05" POWER POLE SURVEY MONUMENT SIGN POST N14'W N62'E S16'W NORTH 26.70' 46.55' 41.25' 17.56' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE HAGNETIC-DISTANCES ARE TO A NAIL W/A DELTA COUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.

LIBER 0009 PAGE 150

Signed by Michigan License No. 16926

Date 2/15/99