

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 39. NR. 18. . . . W

. . . . Delta COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 21 and 22 . . .

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 7" Tamarack (1/4s NBT) S 71° E 27 1/2 Links

10" Cedar (1/4s NBT) S 82° W 56 Links . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced at old wood post set by unknown
surveyor. Distance good to road north and pond to south. No evidence
of original witnesses. Corner lies 14 Links south of Fence corner.
Found by Forestry Division Survey Crew.

Corner was placed and witnessed October 22, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 2/23/60