## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

Description of corner 1/4 corner between Sections 21 and 28

Corner monument 1" Pipe with 4" Brass Cap

Date monument placed and witnessed 9/22/60

Witnesses to corner.....7" Cedar (1/4s NBT) S 26° W 13 Links

N

6" Cedar (1/4s NBT) N 78° W 14 Links

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between Section Corners. No evidence of original corner.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Silly Suckles DATE 5/31/61

REGISTERED LAND SURVEYOR

Billy D. Buckler