

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


DELTA COUNTY
T 39 N R 18 W

DESCRIPTION OF CORNER 1/4 corner for Sections 10³

CORNER MONUMENT 1" pipe with 1/4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED November 24, 1971

WITNESSES TO CORNER..... 10" Balm-of-Gilead (1/8) (BT) S23°E, 25.7'



10" Cedar (Twin) (1/8) (BT) S18°W, 30.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set the proportioned measurement between the section corner to the east and a spring to the west and on a corrected line.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

2-9-72

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68