## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	-	Delta	COUNTY
	•	7 <u>39 N</u>	R <u>18 W</u>
DESCRIPTION OF CORNER	E 1/16 corner for Sections 11		
CORNER MONUMENT	1" iron pipe with h" aluminum	cap	
DATE: MONUMENT PLACED AND W	ITNESSED <u>5/25/71</u> F. J. Bray	·	
WITNESSES TO CORNER	h" Cedar (E 1/16) (BT) N 77°E	2.01	
N	և" Cedar (ይ 1/16) (BT) S 80° Խ		
	AND		
CIRCLE CORNER REGISTERED		<del></del>	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corner to the east and 1/4 corner to the west.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGN

SIGNED REGISTERED LAND SURVEYOR

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing 6/7/71

DATE