

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

DELTA COUNTY


T 39 N R 18 W

DESCRIPTION OF CORNER Section corner for $\frac{10}{11}$
 $\frac{15}{14}$

CORNER MONUMENT 1" axel shaft with 4" hub in place

DATE MONUMENT PLACED AND WITNESSED December 3, 1971

WITNESSES TO CORNER..... 5" W. Spruce (NBT) South, 21.3'



3" Balsam (NBT) S66°E, 17.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by an unknown surveyor. The corner checks well with a stream to the east. Corner location locally accepted.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED _____
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE 1-7-72

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68