

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


DELTA COUNTY
T 39 N R 18 W

DESCRIPTION OF CORNER 1/4 corner for Sections 10/11

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED December 3, 1971

WITNESSES TO CORNER..... 10" Cedar ($\frac{1}{8}$) (NBT) S13°E, 25.5'



14" Cedar ($\frac{1}{8}$) (NBT) N87°W, 30.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set mid-point and on line between the section corners to the north and to the south. Corner lies in a beaver pond.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

1-7-72

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68