

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


DELTA COUNTY
T 39 N R 18 W

DESCRIPTION OF CORNER South 1/16 corner for Sections 10/11

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED December 3, 1971

WITNESSES TO CORNER..... 9" Cedar (S1/16) (BT) S61°W, 78.5'



11" Cedar (S1/16) BT N76°W, 52.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set mid-point and on line between the 1/4 corner to the north and the section corner to the south. Corner lies in a beaver pond.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray DATE 1-7-72
REGISTERED LAND SURVEYOR
Frank J. Bray

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68