LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

	FOR CORNERS OF-:	LOCATED IN-:	CORNER CODE NUMBER	MEITA
	1. PUBLIC LAND SURVEY	T. 39 N. R. 19 E	J-11, K-11, I-12	DELTA CO.
		N. E. W. S., R. — W.		<i>CO</i> .
	ING IN SECTION—— 3. MISCELLANEOUS PROPERTY IN SECTION———	· , i · · · · · · · · · · · · · · · · ·		
	4. LOT NO, RECORDED PLAT			
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
	the corner points mentioned in field survey on September restored as expressed below a of survey instructions of the L court of law. Furthermore	n lines 1 and 2 above (ide 28 1977, established and in conformance with regularity United States Department of that the corner points found, recovered, restored,	entified with circles on index ed, re-established, monuments gulations and rules therefore as of the Interior, Bureau of Land mentioned in lines 3,4 and 5, established or re-established	P.A.74, Michigan P.A. of 1970, code diagram – over) were, in a ed, re-monumented, recovered or a required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in contra or, by a Decree of a Court of
meying S3°E = K-11 - center newer B I-12 -	west. Fence right 29.5' 30.9'; 2634.97' west of N.E. section corner. Mc line of road intersectits soft maple 9" - S	not described in re; fence left 36.0'; section corner of 1917 on, Old Bts. maple 186W - 50.0'; power	ecords. McNabb corner of w. birch 8" - N8 W - 5 sections 25,26,35 and 3 on road traverse - mov 3" - N57 E - 32.4; w. pole - N20 E - 81.7;	36.
		ence found and/or method a	applied in restoring or re-estab	lishing corner:
Pa. as	Set in line with old fe	nce north and 36' no	orth of old E-W fence a	along the south side of Co s recorded distance to
K-11 - constru	Set from old M. McNabb	northeast N.B.T 1	his iron and other N.B.	T.'s destroyed by road
		one fence east and	centerline of road sout	sh and in old cedar boot
fence n J-11 -	C. Description of monument	for corner and accessories cap; face of powe of house foundation	s established to perpetuate loc r pole - S77 E - 140.3' on - Nh1 W - 98.7'; NE	rating the position of the corner: '; 10" stem of tw. coder - cor. of house foundation
K-11 -	1" pipe, 4" aluminum ca of power pole - S17 E -	p buried in road in 83.45'; 5" cedar -	t.; 6" cedar - S69 ⁰ W - S70 ⁰ E - 68.7'; 6" cede	90.h; nail & englin side $ar = N38^{\circ}E = 92.9^{\circ}$.
1-12	1" pipe, " aluminum ca 510°W - 102.5'	p; 5" r. pine -N26	°E = 52.5'; 4" r. pine	- N82°E - 25.1'; 6" apple
			•	
	SIGNED BY	· · · · · · · · · · · · · · · · · · ·	DATE	
	SURVEYOR'S MICHIGAN RE	GISTRATION NO.		(SEAL)
_		TATES AGENCIES:		
	FOR STATE AND UNITED S			
		CHIEF OF SURVEY PARTY	DATE	

FORM APPROVED BY MIGHIGAN STATE BOARD OF REGISTRATION DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERS, CARE

SURVEYOR'S MICHIGAN REGISTRATION NO. _

Form No. MEM736