P.EMONUMENTATION

FEB 2 2 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County	
Land Survey Remonumentation	
Peer Group Under Act 345 Of 2.A. Of 1990 On 10/66, 199	-

ນ ບູກ.	19100	, 199 <u></u>
171	1	1111
Male .	SHAUK	RUS

FC	or corners in			•			
Delta			Located In:		Corner Code ##		
-	(County)		200010		33.1101 3343 44	(A)	
1.	Public Land Survey		т_3	9N _R 21W	D-2	Recorded Ot 27 1995	
			Τ	R		at 9:00 o'clock AM in Liber 8 Page 103	
			T	R		Whaten C. Zhoun Rog. of Deeds.	
			Τ	R		Delta County, Michigan	
2.	Property Controlling	s	T	R			
	in Section	S	T	R			
3.	Miscellaneous	S	T	R		Register of Deeds Stamp & File Number	
	Property in Sec.	S	T	R		riogistal of Docus Stanip & File Hamber	
4.	Lot No	, Recorde	d Plat			A B C D E F G H i i K L	
	• ————————————————————————————————————	-		-		2 6 4 3 2 1	

Robert E. Schmeling, in a field survey on October 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of α Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

8 10 11 12

A. Description of original monument and accessories and/or subsequent restoration: Center ½ corner, Section 5, T39N, R21W which was not set in the original survey of Michigan. Harold Y. Stockholm, U.S.F.S., RLS 23519, on May 13, 1980 found no evidence that corner had been previously established. He established corner by section subdivision survey and set at intersection of straight lines between the opposite quarter corners on the perimeter of Section 5. He set a $2\frac{1}{2}$ ' diameter by 4' long concrete filled galvanized iron pipe 31" in ground; capped with a 3" diameter brass cap stamped to identify corner(found in place this date). He made, blazed, scribed "BT", tagged, and painted witnesses: Maple 12" S44E 22.9 feet(still alive standing tree) and Maple 9" S48W 14.5 feet(still a live standing tree). He set a 4"x4" cedar post 3.1' west of monument with a sign attached (found in place). All his measurements to b of tree and nail and to b of post. His report filed October 30, 1981 in L.5, P.62 of Survey Records, Register of Deeds.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Accepted above monument as the best available evidence of the position of the corner and further improved accessories a/w P.A.345 of Public Acts of 1990.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Witnesses found in place:

Hard Maple 12" S44E 22.9 feet to b of tree and nail(Scribed: BT)

Hard Maple 9" S48W 14.5 feet to b of tree and nail(Scribed: BT)

New witnesses made:

Hard Maple 14" N88E 16.4 feet to b of tree and PK nail(Scribed: C% NBT)

Hard Maple 9" N70W 38.0 feet to b of tree and PK nain(Scribed: C% NBT) Placed iron post 2' nw of monument with warning tag bolted thereon. Placed bearing tree tags on

back side of all four witness trees. All bearings are magnetic.

October 20 , 1995 Signed by _ Date Robert E. Schmeling 8317 Surveyor's Michigan License No FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

8 pare 103

REVISED MAY 14, 1975 REVISED JAN, 1983