SURVEY & REMONUMENTATION

DEC 07 1993

Approved By Delta County Land Survey Remonumentation Peer Group Under Act 345 Of P.A. Of 1990 On Francis 2, 199 3

CON	MAA	500	Chi
- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	/4 t W	1. 7. 3	1

	**************************************	LAID COM		ICATE acting Chairman
For	corners in	Filing Requir	ement of Act 74, Mich. P.	DELTA COUNTY
	DELTA (County)	Located In:	Corner Code ##	LIBER 7 FAGE 328
1.	Public Land Survey	T <u>39 N R 23 W</u> T R T R	K-4 (K-5)	93 DEC -2 AN 9: 00 Walka & Illiana
	Property Controlling in Section	T R S T R S T R		REGISTER OF DEEDS
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
	Lot No , I	Recorded Plat		A B C D E F G H I J K L N
5.	Private Claims	N TO SEC'S 11/12] K-5 [NW COR	SEC 13]	2 6 5 4 3 2 1 1 3
in licur Mar abo Cor exp	hereby certify that under re ines 1 and 2 above were i trent manual of survey insti nagement or by a decree of ove were in conformance w urt of Law; established, pressed below:	, in a field survey onAUGU quirements of P.A. 74, Michigan P.A. n conformance with regulations ar ructions of the United States Depar a Court of Law and/or that the corn- ith the rules of the Michigan Board re-established, monumented, re-	of 1970, the corner points mention of rules therefore as required in timent of the Interior, Bureau of the er points mentioned in lines 3, 4 a of Land Surveyors or by a Decree monumented, recovered, found	ned the the and 7
NO	OTE: Not more than 4 of on this certificate	corners, all in the same town a	nd range, may be recorded	11 12 31 32 33 34 35 36 13
A.	A. Description of original monument and accessories and/or subsequent restoration: K-4 [1/4 COR COMMON TO SEC'S 11/12] WOOD POST - A, MERRYWEATHER -1846 (BIRCH 10"-S50"E-6 LINKS) (HEMLOCK 12"-N40"W-10 LINKS) D.A. BROTHERTON - 1907 - ID FROM ORIGINALS - NBT BEECH 8"-N60"E-38.5 M.S. McNABB - 1926 - WCOD STAKE IN PLACE - COR FENCE POSTS - WEST 30.7' & EAST 16' M. DAVIS - 1970 - FOUND IRON PIN IN PLACE - L.C.R'S IN LIBER 4 ON PAGE 185 K-5 [NW COR SEC 13] WOOD POST - A. MERRYWEATHER - 1846 (BIRCH 7"-S50"W - 24 LINKS) (MAPLE 8'-N73'E-8 LINKS) M.S. McNABB - 1915 - ID FROM BOTH ORIGINALS - SET I.P. 5' LONG FOR COR - NO WIT'S NOTED			
В.	Description of corner K-4 [1/4 COR COMMON TO	8 - FOUND 1-1/4" I.P L.C.R'S evidence found and/or method SEC'S 11/12] FOUND IRON PIN NUMENT AS BEING A CAREFUL & FA	applied in restoring or reestance AS DESCRIBED IN L.C.R'S LIBER	4 PAGE 185 - 15" BELOW EXISTING ROAD SURFACE
		COUND 1-1/4" IRON PIPE AS DESCR PION OF THE POSITION OF THE ORI		208 - ACCEPTED CORNER MONUMENT AS BEING A CAREFUL M. P. DAVIS LAND SURVEYOR NO. 16926
C.	Description of monum	ent for corner and accessories	established to perpetuate lo	cating the position of the corner:
	POWER POLE BI N35°W	EECH 15" ANCHOR POLE N64°E \$40°E	SURVEY MONUMENT SIGN POST S60°W	CAP STAMPED TO ID THE COR POSITION
	40.25'	42.35' 35.75'	34.90' (TO FACE)	
	K-5 SET, OVER EXISTING SURVEY MONUMENT S S45'E 1.21' (TO FA	NOTE: ALL BT'S SHO		D THE COR POSITION OR ARE STILL GREEN & VIALBLE
	NOTE: BEARINGS TO REF	ERENCE OBJECTS ARE MAGNETIC & D	ISTANCE ARE TO A NAIL IN THE	CENTER OF THE OBJECT UNLESS NOTED OTHERWISE
Sig	gned by		Date	10/30/93
Su	ırveyor's Michigan Licer	ise No. 16976		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19