14.17 b 2003

SECTION

Surveyor's Michigan License No. 16976

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

Approved by Delia County
Land Survey Remonumentation
Peer Group Under Act 345 Of .
P.A. Of 1990 On 3-3, 1999
Wanie B. Bollet

- 3€0/110/1 -	Filing Require	ement of Act 74, Mich. P	.A. 1970	Chairman
For corners in DELTA		·		
County;	Located In:	Corner Code ##		
-County			m .	4 1999
Public Land Survey	T 39 N R 18 W	E - 1 SAME	9:00	AU
	T 40 N R 18 W	E - 13 CORNER V	3 1.00 3 cm	\
	T <u>39 N</u> R <u>18 W</u>	E - 2	The Trees.	/37
	T R		jibelin	
Property Controlling	S T R		ी के दिलांस से दिखें वा दिख	· ·
in Section	S T R			
Miscellaneous	S T R		Register of Deeds	Stamp & File Numb
Property in Sec.	S T R		·	
Lot No	Recorded Plat			* * * * * * * * * * * * * * * * * * * *
Drivate Claims	Trocorded Flat		A B C D	E F G H I J I
Frivate Otalina			2 - 6 - 5-	4
	E-1 [NW COR SEC 4] E-2 [W1/4 C	OR SEC 41	3	
		· · · · · · · · · · · · · · · · · · ·	4 7 7 8-	9 10 11
M.P. DAVIS	_ , in a field survey onFEBRUA	RY . 19 99	, 5	
hereby certify that under r	equirements of P.A. 74, Michigan P.A.	. of 1970, the corner points menti	ioned g	16 15 14
lines 1 and 2 above were	in conformance with regulations ar	nd rules therefore as required i	in the	
irrent manual of survey ins	tructions of the United States Depar of a Court of Law and/or that the corne	tment of the Interior, Bureau of	Lario F-T-1	
anagement or by a decree o Nove were in conformance (or a Court or Law and/or that the come with the rules of the Michigan Board (of Land Surveyors or by a Decre	enfa III	21 22 23
ourt of Law; established,	re-established, monumented, re-	monumented, recovered, four	nd as	1 1 1 1
pressed below:			10 30 29	28 27 26
OTE: Not more than 4	corners, all in the same town a	nd range, may be recorded	11	
on this certificate			12 31-32	33 34 35
	I monument and accessories an		13	
M.DAVID, KBC 1772 B.	1 PG.22 LCR'S-FOUND IN PLACE STO	nay from 11k ar vot or 12kos		are diminary
E-1 [NW COR SEC. 4] FO AT L.4 OF LCR'S PG. FOUND IN PLACE TO T	evidence found and/or method UND IN PLACE AT THE JCT OF FARM 213. THIS MONUMENT CHECKS WELL F HE SOUTH. ACCEPTED EXISTING MONU POSITION OF THE ORIGINAL CORNER.	FENCES N-S & E-W A 1" IRON I OR POSITIONAL MEASUREMENTS! MENT AS BEING THE BEST AVAIL	PIPE AS DESCRIBED TO 1/16 & 1/4 CORNERS	OF MICA
BY MYSELF IN 1972 AMBASUREMENTS TO ADJUST OCCUPATION. ACCEPTED	OUND IN PLACE A 1" IRON PIN. ID ND REC'D IN L.1 OF LCR'S PG.22. DINING CORNERS FOUND TO THE NORT DEXISTING MONUMENT AS BEING TEE THE ORIGINAL CORNER.	THIS MONUMENT CHECKS WELL WITH & SOUTH AND FITS WELL WITH	ITH POSITIONAL #6	M. P. DAVIS LAND SURVEYOR NO.
				16926 CARED LAND SUR
	nent for corner and accessories MONUMENT, A BERNTSEN AINB30 ALUM SURVEY MONUMENT SIGN POST NORTH 0.91' (TO FACE)	MONUMENT W/A 3x/4" CAP STAN	MPED TO ID THE CORNER POS FOUR QUADRANTS.	
•	NONUMENT, A BERNTSEN AINB30 ALUM FENCE LINE EAST FENCE LINE WE NORTH SOUTH	N MON. W/A 31/4" CAP STAMPE ST DRILL HOLE IN LARGE ROU SOUTH		
2'±	6'± 8'±	22.90'	0.84' (TO FA	CE)
NOTE: BEARINGS TO REFER	ENCE OBJECTS ARE MAGNETIC-DISTAN	CES ARE TO A NAIL W/A DELTA	COUNTY REFERENCE TAG, UN	•
igned by	ANUS	Date	2/15/99	