## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	Delta	COUNTY
	T 140 N	R <u>18 W</u>
DESCRIPTION OF CORNER _ 1/2 corner for sections 33/34		
CORNER MONUMENT 1" iron pipe with 4" aluminum	cap	
DATE MONUMENT PLACED AND WITNESSED 11/6/70 F. J. E	Bray	
WITNESSES TO CORNER 6" R. Maple (なら) (NBT) N	75° E, 7.9'	
N 6" R. Maple (% S) (NBT) S	23° E, 7.7'	
AND		
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two rotted stump bottoms in proper bearing and distance as recorded in original field notes. Checks well with section corners to north and to south.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR

DATE 12-3-70

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68