

✓

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


\_\_\_\_\_ DELTA \_\_\_\_\_ COUNTY  
T 40 N R 18 W

DESCRIPTION OF CORNER North 1/16 corner between Sections 28/27

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED November 15, 1971

WITNESSES TO CORNER..... 10" Hemlock (N1/16) (BT) S40°W, 55.8'



9" Hemlock (N1/16) (BT) N58°W, 35.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set mid-point and on line between the 1/4 corner to the south and the section corner to the north. Corner lies on the west edge of the road to the new Garden Township dump.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

1-7-72

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68