## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	DI	ELTA	COUNTY
	T40_	<u>N</u> R_	18 W
DESCRIPTION OF CORNER West 1/16 corner for Section	ns 25		
CORNER MONUMENT 1" pipe with 4" aluminum cap			
DATE MONUMENT PLACED AND WITNESSED December 2, 1971	1 11 61		
WITNESSES TO CORNER 5" Gedar (W1/16) (BT) NO50	V. 11.0.		<u></u>
5" Cedar (W1/16) (BT) N80°	E, 7.51		
AND			
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set mid-point and on line between the section corner to the west and the 1/h corner to the east.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR

**DATE**  $\frac{1-7-72}{}$ 

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing