STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		DELŢA	COUNTY
	T 40	<u> N</u>	R <u>18 W</u>
DESCRIPTION OF CORNER 1/4 corner for Sections 25			
CORNER MONUMENT 1" pipe with 4" aluminum cap			
DATE MONUMENT PLACED AND WITNESSED December 2, 1971	<u></u>		
WITNESSES TO CORNER 3" Cedar (S) (NBT) East, 8	•3¹	<u> </u>	
3" Cedar (3s) (NBT) So8°, 4,	.51		
AND			<u> </u>
CIRCLE CORNER REGISTERED DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND	IDENTIF	IED OR RE	ESTORED.

This corner was set mid-point and on line between the section corners to the east and to the west.

SURVEYOR'S SEAL

SIGNED

D REGISTERED LAND SURVEY

Frank J. Bray

DATE __

<u>1-7-72</u>

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68