

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


DELTA COUNTY  
T 40 N R 18 W

DESCRIPTION OF CORNER 1/4 corner for Sections <sup>22</sup>/<sub>27</sub>

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED November 23, 1971

WITNESSES TO CORNER..... 3" Hemlock ( $\frac{1}{8}$ S) (NBT) N85°W, 8.0'



5" Hemlock ( $\frac{1}{8}$ S) (NBT) S32°E, 5.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set mid-point and on line between the section corners to the east and to the west. Two old posts and a picket line to the south. No evidence of original corner.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

*Frank J. Bray*  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

1-7-72

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68