STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	D-14- COINTY
	<u>Delta</u> COUNTY T 40 N R 18 W
	T 40 N R 18 W
DESCRIPTION OF CORNER Sou	th 1/16 28/27
CORNER MONUMENT 1" iron pipe with 4" aluminum cap	
DATE MONUMENT PLACED AND WI	TNESSED <u>8/26/71 F. J. Bray</u>
WITNESSES TO CORNER	h" Balsam (S1/16) (BT) S 50° W, 2.31
N -	8" W. Spruce (S1/16) BT N 27° W. 15.6'
27	5" Balsam squared and scribed for corner post, N 27° W, 2.3'
A A	ND
CIRCLE CORNER REGISTERED	
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.	
This corner was mid-point on line between the 1/4 corner to the north and the	
section corner to the south.	
SURVEYOR'S SEAL	•
DISTRIBUTION:	REGISTERED LAND SURVEYOR Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing