

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Delta COUNTY
40
T 39 N R 18 W

DESCRIPTION OF CORNER $\frac{35}{4}$ corner for sections 2 $T_{39}N, R_{18}W$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 11/10/70 F. J. Bray

WITNESSES TO CORNER..... 6" Cedar ($\frac{1}{4}$ S) (NBT) N 44° E, 33.8'



11" Tamarack ($\frac{1}{4}$ S) (NBT) S 11° E, 33.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners to east and to west.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR

DATE

12-7-70

Frank J. Bray

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68