## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**



## LAND CORNER RECORD

			Del.ta	COUNTY
		т	<u>цо</u> 39 N	R 18 W
DESCRIPTION OF CORNER <u>遠</u> c	orner for sections	34 Thon, R18		
CORNER MONUMENT1"	iron pipe with 4"	aluminum cap		
DATE MONUMENT PLACED AND WITNESSED 11/10/70 F. J. Bray				
VITNESSES TO CORNER	6" W. Pine (½S) (1	NBT) N 45° W,	, 19.31	
N 3 -	5" W. Pine (太S) (	NBT) S 21°W,	, 6,5'	
T59N R18W		.,,	<del> </del>	
ANI	)			
CIRCLE CORNER REGISTERED				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners to east and to west.

SURVEYOR'S SEAL

SIGNED

DATE

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68